(Following Paper ID				-			
PAPER ID : 2938	Roll No.						

B. Tech.

(SEM. VIII) THEORY EXAMINATION 2011-12

SIX SIGMA METHODS AND APPLICATIONS

Time: 3 Hours

Total Marks: 100

- Note:—(1) Attempt all questions.
 - (2) All questions carry equal marks.
 - (3) Be precise in your answer.
- 1. Attempt any four of the following questions:— (5×4=20)
 - (a) What activities are to be performed for quality in manufacturing and in service sector?
 - (b) Briefly write the Six Sigma Success Story of General Electric.
 - (c) What do you mean by quality improvement? Write diagnostic methods to test theories of management-controllable problems.
 - (d) What is inferential statistics? Define median, range, standard deviation and Kurtosis.
 - (e) What is histogram? How it is constructed?
 - (f) Explain binomial distribution.
- 2. Attempt any four of the following questions: (5×4=20)
 - (a) Explain the concept of six sigma system.
 - (b) Define defect and explain sporadic condition and approach for handling sporadic problems.

EME055/PUR-40304

1

[Turn Over

(c) A process produces 40,000 pencils. Three type of defects. can occur. The number of occurrence of each defect type are:

Blurred printing (as pencil slips in the fixture)

= 36

Wrong dimension (at three independent place)

= 118

Rolled ends (at top and/or bottom)

= 11

Find out DPMO

- (d) Explain customer focus.
- (e) What are service-processes and explain "Six Sigma Services" challenge?
- (f) Explain the role of Master Black Belts, Black Belts and Green Belts in a six sigma organisation.
- Attempt any two of the following questions: 3.

 $(10 \times 2 = 20)$

- (a) What is DMAIC? Explain DMAIC Team Life Cycle Phases.
- (b) Explain DFSS methodologies and DFX.
- (c) Explain three basic approaches for implementing Six Sigma.
- Attempt any two of the following questions: (10×2=20) 4.
 - (a) What is Process Map and how it is created?
 - (b) What is hypothesis testing? Write the procedure for testing hypothesis. A single-cavity moulding press has

EME055/PUR-40304

been producing insulators with a mean impact strength of 5.15 Nm and with standard deviation of 0.25 Nm. A new lot shows the following data from 12 specimen:—

Specimen No.	Strength					
1	5.02					
2	4.87					
3	4.95					
4	4.88					
5	5.01					
6	4.93					
7	4.91					
8	5.09					
9	4.96					
10	4.89					
11	5.06					
12	4.85					

Is the new lot from which the sample of 12 was taken different in mean impact strength from the past performance of the process, considering type-I error of 5%. Given z-score of -1.96 for proportion area of 0.0250 under normal distribution curve.

(c) What is QFD and FMEA? How to perform FMEA?

EME055/PUR-40304

3

[Turn Over

- 5. Attempt any two of the following questions:—(10×2=20)
 - (a) How to sustain Six Sigma Improvement?
 - (b) What are the various softwares developed for Six Sigma ? Explain Minitab.
 - (c) Explain various graphical analysis of minitab plots.

EME055/PUR-40304

6350